

Шаг для основной и мелкой резьбы

Резьба	Шаг резьбы P, мм			
	Основная резьба М	Мелкая резьба М		
		мелкая	мелкая 2	супермелкая
M1	0.25	(0.2)		
M1.2	0.25	(0.2)		
M1.4	0.3	(0.2)		
M1.6	0.35	(0.2)		
M1.8	0.35	(0.2)		
M2	0.4	(0.25)		
M2.2	0.45	(0.25)		
M2.5	0.45	(0.35)		
M3	0.5	(0.35)		
M3.5	0.6	(0.35)		
M4	0.7	0.5		
M5	0.8	0.5		
M6	1.0	0.75	0.5	
M8	1.25	1.0	0.75	0.5
M10	1.5	1.25	1.0	0.75
M12	1.75	1.5	1.25	1.0
M14	2.0	1.5	1.25	1.0
M16	2.0	1.5		1.0
M18	2.5	2.0	1.5	1.0
M20	2.5	2.0	1.5	1.0
M22	2.5	2.0	1.5	1.0
M24	3.0	2.0	1.5	1.0
M27	3.0	2.0	1.5	(1.0)
M30	3.5	2.0	1.5	(1.0)
M33	3.5	2.0	1.5	
M36	4.0	3.0	2.0	1.5
M39	4.0	3.0	2.0	1.5
M42	4.5	(4.0) 3.0	2.0	1.5
M45	4.5	(4.0) 3.0	2.0	1.5
M48	5.0	(4.0) 3.0	2.0	1.5
M52	5.0	(4.0) 3.0	2.0	1.5
M56	5.5	4.0	3.0 (2.0)	1.5
M60	5.5	4.0	3.0 (2.0)	1.5
M64	6.0	4.0	3.0	2.0 (1.5)
M68	6.0	4.0	3.0	2.0 (1.5)